

~30% of the Building
Resources of past
Civilizations were
Spent on Drainage



This was Caused by Poor
Grading, Clogged
Downspouts & a Clogged
Foundation Drain




Drain Designs

Smart Drainage Solutions





1-800-DRAINAGE



The Corner of this
Building, Undermined by
a Clogged Downspout

Yard Flooding,
Damaging Driveway
& Foundation





Flooded,
Clogged
French Drain

Wet Soil Expands and Cracks Foundation



A photograph showing a person in work clothes and gloves working in a trench. They are using a tool to clear a large, dark, clogged corrugated pipe. The pipe is surrounded by dirt and dry leaves. In the background, there are some plants and a building.

This Clogged Corrugated
Downspout Pipe was
backing up & Damaging
the Foundation.

Clogged Corrugated Pipe



The Sump Pump
can't Keep Up






Downspout Drains and Surface Drains help Prevent Erosion & Yard Flooding



**Standing Water causes Basement
Flooding/ Wetness and Mosquitoes**

New Corrugated, Still
Bad - Leaky Systems
Cause Foundation/
Structural Problems &
Mold





Waterproof the Basement Right the 1st time for \$16,000... So you don't need to do it the 2nd time for \$60,000

A photograph of a white downspout attached to a stone wall. The downspout has a black outlet cap at the bottom. Water is leaking out from the bottom of the cap, indicating a clog. The downspout is situated on a grassy area next to a stone wall. A white text box with blue text is overlaid at the bottom of the image.

Sign of a Clogged Downspout